Bulletin No.: PIT5996
Published date: 03/29/2023

Preliminary Information

PIT5996 Diagnostic Tip: Unable To Perform Lighting Control Module Special Function Tests With GDS Scan Tool.

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Brightdrop	Zevo600	2023	All	All	All	All
Cadillac	LYRIQ	2023	All	All	All	All
GMC	HUMMER EV	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	
Condition	**When performing diagnosis on one of the following vehicles listed above, technicians may notice that none of the special functions that are listed under the K219 Lighting Control module are currently working with the GDS2 scan tool and you may get a pop screen like the picture below.**
Cause	**This is due to an software anomaly in the K219 Lighting Control module**



Correction:

If you experience this concern, please do not replace the K219 Lighting Control module. Engineering is aware of the issue and they will be releasing software in the future to address this concern. This issue will only inhibit GDS2 test functions and will not affect normal operation of the K219 Lighting Control Module.

Warranty Information

Version History

Version	**1**
Modified	03/29/2023 - Created on.

GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.