VOLVO

TRUCKS DEALER BULLETIN

To:	General Managers, Service Managers, Service Technicians, Warranty Managers
From:	Volvo Trucks – Service
Date:	April 30, 2023
Subject:	Service Literature Published and Released in April, 2023
Bulletin:	SLV23-004

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TOOL BULLETINS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TECHNICAL SERVICE BULLETINS

BULLETIN #	TITLE	COMMENTS
V-366-008	Adaptive Cruise Control, Deactivation	New
V-212-003	Timing Gear Plate, Inspection and Repair	Update
V-773-005a	Hub Cap, Leaking	Update

SERVICE PROGRAMS

BULLETIN #	TITLE	COMMENTS
S2936	Anti-lock Braking System (ABS) Software Update and Inspection	Update

RECALLS

BULLETIN #	TITLE	COMMENTS
	None Issued	

© 2023 Volvo Group North America, LLC. CONFIDENTIAL - For limited distribution only to circulation list above. This bulletin, and any information herein, is subject to change by Company without notice. For the most current and accurate information, always refer to Trucks Dealer Portal for the electronic version of this document.

VOLVO

TRUCKS DEALER BULLETIN

CASE BASED REASONING (CBR)

NEW SOLUTIONS

SOLUTION #	TITLE
CBR-2255	Battery Electric Vehicle (BEV) Cab Heater Diagnostics
CBR-2262	Volvo - Transmission Will Not Shift Into 12TH Gear Under A Load
CBR-2265	Volvo VHD Models - Allison Reduced Engine Load At A Stop (RELS) Diagnostic Trouble Code P071A Or P07CE - Non-Split/Drop Box PTO
CBR-2269	11L Engines, Non-Common Rail - Air Compressor Coolant Pipe, Substitution - US14+OBD13 To US14+OBD16
CBR-2271	Volvo Chassis - BEV PC04 VNRe ESS (Traction Battery) Locations
CBR-2272	Diagnostic Trouble Code (DTC) P008A - Low Pressure Fuel System Pressure - Too Low
CBR-2274	Volvo - Pre-Delivery Inspection (PDI) Torque Values
CBR-2275	Volvo Chassis - Battery Electric Vehicle (BEV) Diagnostic Trouble Code (DTC) C10019E - Electric Vehicle Air Compressor 1, Stuck On

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-2033	Volvo On-Highway Vehicles - Bendix ABS Fault SPN 807 FMI 13 Blink code 19-4	Updated images to reflect current Trucks Dealer Portal layout
CBR-2191	Volvo NOx Sensor Troubleshooting Guide - US10+OBD13 And Newer Emissions	Changed description for DTC P220513 from "outlet" to "inlet". Added P113600 under outlet NOx yellow code list. Expanded tag list to improve searchability. Reorganized and reformatted article and charts for improved readability.
CBR-2260	Volvo Chassis - Timing Gear Plate Repair	Added video of the repair procedure; updated tags for improved searchability.

© 2023 Volvo Group North America, LLC. CONFIDENTIAL - For limited distribution only to circulation list above. This bulletin, and any information herein, is subject to change by Company without notice. For the most current and accurate information, always refer to Trucks Dealer Portal for the electronic version of this document.