Bulletin #: C32-0223-0611	☐ Take Note ☒ Take Action
☐ Retail Operator ☐ Sales Pre-Owned	☐ Business Manager ☒ Parts & Accessories
☐ General Manager ☐ Sales New Car	☐ Service ☐ Administration
Name: Kenny Inoa	Phone Number: 201-571-5623
Title: Material Flow & Inventory Integrity	Source: Parts Logistics
Date: February 8, 2023	Supersedes:

The Ultimate Driving Machine®

BMW PARTS BULLETIN

TEC509 RIGHT SIDE OUTER WEATHERSTRIP RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

51 22 1 960 848


Affected inventory must not be sold or installed on any vehicle.

Concerned are all parts shipped and delivered so far with incorrect length (example 835mm). Correct part must have a length of 593mm (+1,5mm;-0,5mm) and pn 1960848 is printed on the part.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC509 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC509 is valid from February 8, 2023, through February 22, 2023. The deadline for filing a claim under TEC509 is February 22, 2023. All parts must be returned to your facing RDC no later than March 8, 2023.

Please reorder the same part number if needed.



© 2023 BMW of North America, LLC. The contents of this document are confidential and should not be shared with third parties for distribution.