# SERVICE BULLETIN

**M1594** **2023-06-29**

## M1594: TEMPORARY WIRE COLOR DEVIATION IN HAND CONTROL MODULE HARNESS

### Reason for Revision

Refer to Table 1.

**Table 1. Document History**

| Date | Rev | Revision (Rev) Description |
|---|---|---|
| 2023-06-29 | - | Initial release |

### Purpose for Service Bulletin

To inform dealers that there is a temporary change to the wire colors, from what is shown in the Electrical Diagnostic Manual (EDM), on the Right Hand Control Module (RHCM) and Left Hand Control Module (LHCM) wire harnesses due to a wire shortage at the supplier. Once supply has been replenished the wire colors will go back to matching the information provided in the EDM.

### Vehicles Affected

2023: CVO Street Glide (FLHXSE), CVO Road Glide (FLTRXSE)

### Markets Affected

All markets affected.

### Part Numbers

Refer to Table 2.

**Table 2. Part Numbers**

| Affected Part No. | Item Description |
|---|---|
| 69203018 | RHCM |
| 69203017 | LHCM |

### Required Dealer Action

**Table 3.**

| Action Required | Resolution |
|---|---|
| NO ☑<br>YES ☐ | **Non-Actionable:**<br>This is for informational purposes only or a technical tip. |

RHCM Harness (Part No. 69203018):

- BN (Brown) wire from connector [22B] pin 8 to connector [170B] pin 3 will be colored O(Orange)

LHCM Harness (Part No. 69203017):

- BN (Brown) wire from connector [24B-1] pin 8 to connector [314B] pin 3 will be colored O(Orange)
- TN (Tan) wire from connector [24B-1] pin 7 to connector [314B] pin 4 will be colored Y (Yellow)

*NOTE*

*In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.*

| ROUTING | SERVICE MANAGER | SALES MANAGER | PARTS MANAGER | WARRANTY PROCESS MANAGER | LEAD TECHNICIAN | TECHNICIAN NO. 1 | TECHNICIAN NO. 2 | TECHNICIAN NO. 3 | RETURN THIS TO |
|---|---|---|---|---|---|---|---|---|---|
| INITIAL HERE | | | | | | | | | |