2023 Ascent

1.COMPLAINT: LP SYSTEM FAIL LEAK IN HOSE NEAR REGULATOR
CAUSE:LEAK
CORRECTION: Did a LP drop test 3x and failed all 3x. System has a leak and did further diag with soapy water and found a leak. Puncture in the hose attached to Regulator. Recommend replacing LP hose. LABOR: 4.0 HOURS LABOR PARTS: LP HOSE 1.0 approved This hose as well is just screwed in on both sides. We will send you the hose so please do NOT order.

0