2023 Plateau

Complaint- C/S there is a water leak from bath faucet under sink.
Cause- Confirmed. Bath faucet is leaking internally.
Correction- R/R faucet. Requesting 0.5 0.5 approved.

The time approved is 0.5 hour (0.3 R/R + 0.2 diag.) the bathroom faucet.