Technical Service Bulletin

Technical Service Bulletin: TSB230168	**Released Date**: 05-Sep-2023
Fault Code 3243	

Fault Code 3243

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2450 B155B (Hybrid Transit Bus Application **Only**)

Issue Summary

Symptom:

- Fault Code 3243

Root Cause:

- False occurrences of Fault Code 3243

Verification

Compare the ECM code and revision number in the ECM to the calibration revision listed in the ECM Calibration Revision History Database on QuickServe® Online (QSOL) for applicable changes.

Resolution

- If an ECM calibration code update for this fault code is available, the ECM calibration code revision **must** be that revision or higher.
- If the ECM calibration code revision is up-to-date, proceed with published troubleshooting tree.

Document History

Date	Details
2023-9-5	Module Created

Last Modified: 05-Sep-2023