2023 Ontour

REPAIR 3: bathroom door rattles. striker too far forward. Move striker further back and test functions. REQUESTING: .3 HRS 0.20 approved.

2023 Ontour

Line 1: DRAWERS

Complaint: CUSTOMER STATES ALL 3 DRAWERS UNDER STOVE TOP OPEN IN TRANSIT

Cause: TOP INNER CABINET CATCHES MOUNTED TO HIGH-LOSING CONTACT WITH CATCHES

Correction: R/I CATCH AND ADDED SHIMS TO LOWER CATCH FOR PROPER FIT AND OPERATION. TESTED=OKAY.

Labor request: 0.50 0.50 approved.