SIB 13 03 23 2023-11-08

SERVICE SOLUTION: DISA Errors 0x3A14C2 and 0x3A14C5

MODEL

Any model with DISA servomotor.

SITUATION

With the ignition ON, the unfiltered air flap and the variable length intake manifold are activated. With a weak or defective battery, these faults are stored in the engine control unit. (0x3A14C2 and 0x3A14C5). In addition there is a fault displayed in the instrument cluster.

PROCEDURE

Note: Always charge and test the battery. If necessary, replace it. (In order to determine if the battery is warrantied please refer to the current Warranty Policy and Procedures Manual (WPPM).)

Guided diagnostics must be carried out with ISTA.

The sensitivity of the faults were adapted from I-Level K001 22-07-511 and newer. Program the vehicle if necessary.

If the errors are still present for the DISA, please create a TSARA case for escalation.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials
picture_as_pdf 13 03 23 - Service Solution - DISA Errors 0x3A14C2 and 0x3A14C5.pdf

Copyright ©2023 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved

Copyright ©2023 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved