2023 Ontour

Concern: Co detector button pushed in and will no come out

Cause: Broken button

Correction: R&R detector lp/co alarm

Time: 0.4 hours

2022 Ascent

C/S LP DETECTOR COMING ON INTERMITENLY
DEFECTIVE CO DETECTOR
NEED TO R&R CO DETECTOR

HOURS .50 0.3 approved to R/R CO/LP detector.