SERVICE BULLETIN

M1613: 2023 CVO STREET GLIDE (FLHXSE) BRAKE AND CLUTCH LINE CLIP RETENTION

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2023-11-01	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that Harley-Davidson has observed on the 2023 CVO Street Glide (FLHXSE), poor retention of the brake and clutch line clip, located on the right side of the steering head.

Vehicles Affected

2023 CVO: Street Glide (FLHXSE)

Markets Affected

All markets affected.

Part Numbers

Refer to Table 2.

Table 2. Part Numbers

Part No.	Item Description
10039	Cable strap

Required Dealer Action

Table 3.

Action Required	Resolution
NO ☑ YES ☐	**Non-Actionable:** This is for informational purposes only or a technical tip.

If poor retention of the brake and clutch line clip is observed, a Cable Strap (Part No. 10039) may be used to retain the clip in its intended location.

1. See Figure 1. Poor retention of the brake and clutch line clip (2) is observed.

1. **Harness caddy**
2. **Line clip**

Figure 1. Line Clip Popping Out of Harness Caddy

2. See Figure 2. Secure line clip (1) to caddy and install cable strap (2).

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

1. Line clip
2. Cable strap

Figure 2. Cable Strap Installed