Bulletin No.: PIC6535
Published date: 12/21/2023

Preliminary Information

PIC6535 False Automatic Emergency Braking (AEB) Events

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XT4	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UHY, UKT
Condition	Customer may comment on unwanted Automatic Emergency Braking events and alarms in non-collision circumstances
Cause	Front view camera module - windshield calibration

Correction:

Do not replace the Front Camera Module - windshield for this concern.

Engineering is working on new calibrations.

Until the new calibration is released, customers who experience this concern can disable Automatic Emergency Braking in the vehicles personalization settings.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2886018	Confirm the FVCM has no issues or DTC's that would contribute to the false AEB event	0.1 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	12/21/2023 - Created on.

© 2024 General Motors. All Rights Reserved.