Tesla, Inc. Service Bulletin		Replace Front Body Controller Module		
SB-23-17-011 February 2, 2024	R1			
Classification		**Section/Group**	**Mobile Service**	**Configuration**
Campaign Bulletin		17 - Electrical	Can Perform (where permitted)	All
Model Year	**Model**	**Country/Region**	**Build Location**	
2023	Model Y	United States, Canada	Fremont, Giga Austin	
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.				

Campaign Bulletin: This campaign bulletin addresses a non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to the applicable vehicles.

This Service Document supersedes SB-23-17-011, dated November 9, 2023. This new revision, R1, adds a note and removes one of the correction codes. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

Certain Model Y vehicles may require replacement of the front body controller module which may impact the ability to detect fuse failure and show an alert for “Condition detected with a vehicle controller”.

Correction

Replace the front body controller module.

NOTE: If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time
Replace Front Body Controller Module	S022317011	0.96

	Part Number	Description	Quantity
Parts Required		**One of the following:**	
	1866750-00-A	ASY. FRONT CONTROLLER GEN 3	1
	1866750-20-A	ASY. FRONT CONTROLLER GEN 3	1
	1886750-99-A	RWK ASY. FRONT CONTROLLER GEN 3	1
		And:	
	1137934-00-C	BOLT - HF - M6X16 - [109] - G0109 - ADH - MAT	2
	1128091-00-B	SCREW HF M6X16	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog.

Procedure

Replace the front body controller module (refer to Service Manual procedure 17152912).

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com