Bulletin No.: PIT6093A
Published date: 03/15/2024

Preliminary Information

PIT6093A Drivers Window Does Not Fully Close

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer EV	2024	All	All	All	All

Involved Region or Country	North America
Condition	A customer or technician may notice that the driver's window does not fully close, leaving a 4 mm gap at the top. A customer may complain of a wind noise from the driver's window. This condition may be intermittent. It may be found that this condition occurs after using the express up feature. It may also be noticed that the window goes up an additional 4 mm, after an auto stop.
Cause	Calibrations

Correction:
If this condition is found program the K9 Body Control Module with the latest software.

Version History

Version	2
Modified	11/29/2023 - Created on. 03/15/2024 - PIT6093A created to change Correction to program the BCM per BQM.

GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.