2025 Ontour

COMPLAINT: Two drawers coming loose while driving
CAUSE: Out of adjustment
CORRECTION: Adjusted the two drawers under the sink.
LABOR: 0.4 0.40 approved.
PARTS: none

2025 Ontour

.50 0.30 approved.

THE 2 CABINETS BEHIND THE PASSENGER SEAT RATTLE WHILE DRIVING. DOOR NOT CLOSING CORRECTLY. ADJUSTED HINGES TO CLOSE COMPLETELY