Field Action Number	N25-250403
Release notes	• Improves Check Engine Light accuracy. • Improves behavior of aero shutter system in freezing temperatures. During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.
Model Year	2024
Make	GMC
Model	Sierra HD Crew Cab
Components	ECM (Engine Control Module)