SERVICE BULLETIN

M1707 2025-12-09

M1707 (REV A): 2025 SOFTAIL BCM UPDATE

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2025-12-09	A	Add 2026 Softail models (Until Build Date of December 15, 2025)
		* Updated: Vehicles Affected
2025-11-21	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that there is a Body Control Module (BCM) update available for 2025 Softail models. This update will be available in Digital Technician II (DT II) version 26.0.1 or later. This update is to address a number of concerns and also provide functional improvements.

Table 2. Software Version

Previous Software Version	Updated Software Version
16.04.11.02	16.05.11.02

BCM update release notes:

- Update to Turn Signal Cancellation processing
- Consistency in FOG lamp operation over an ignition cycle
- Fault recovery and Diagnostic Trouble Code (DTC) setting updates
- Other various updates

Required Dealer Action

Table 3. Required Dealer Action

Category	Description	Required
1	Must Perform Repair	☐
2	Repair If Presenting Symptom	☑
3	Feature Pack-Customer/Dealer Paid	☐
4	Informational Purposes Only	☐

If a vehicle arrives with any of these symptoms, connect DT II and follow steps to reflash the BCM.

Warranty can only be claimed if the vehicle exhibits these symptoms.

Vehicles Affected

2025: Heritage Classic (FLHC), Fat Boy (FLFB), Breakout (FXBR), Street Bob (FXBB), Low Rider S (FXLRS), Low Rider ST (FXLRST), Fat Boy Gray Ghost (FLSTFI)

2026 (Until Build Date of December 15, 2025): Heritage Classic (FLHC), Fat Boy (FLFB), Breakout (FXBR), Street Bob (FXBB), Low Rider S (FXLRS), Low Rider ST (FXLRST)

Markets Affected

All markets affected.

Affected Part Numbers

Refer to Table 4.

Table 4. Part Numbers

Part No.	Item Description
41001557	MODULE, BODY CONT, 2GII, 3-AXIS, 434 MHZ
41001558	MODULE, BODY CONT, 2GII, 3-AXIS, 315 MHZ

Credit Procedure

NOTE

Enter bulletin number in Events Comments.

File a Warranty claim per Table 5 for completing the work and note the customer's concern in the comments section of the claim.

Table 5. 2025 Softail BCM

ITEM	DATA
Claim Type	PRD/MC/DEM - PDI/Standard Claim
Problem Part Number	41001557 or 41001558
Quantity	Leave Blank
Labor Code(1)	1746
Labor Time	0.2 hours
Customer Concern Code	9203
Condition Code	1746
(1) Download may be required	

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									