PRELIMINARY INFORMATION

Subject: BCM Software Reconfiguration Currently Unavailable

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	**to**	**from**	**to**		
Chevrolet	Silverado 1500 LD	2025		All	All	All	All
GMC	Sierra 1500 LD	2025		All	All	All	All

Involved Region or Country	North America
Condition	Some dealers may comment that after reprogramming the BCM to add or change one of the following options/accessories that now they are having issues with the SDAC not completing, BCM programming errors, etc. In addition, TCSC currently will not provide BCM calibrations to add/change any of the following options/accessories: • Fast Flash (bulb outage detection) Removal (ZW9) • Remote Start Add • Speed Governor Changes (adding or removing) • Police Vehicle Reconfigurations • High Idle (UF3) • Engine Timeout Disable (SK4)
Cause	Due to an issue with the release of the BCM calibrations these reconfigurations were temporarily placed on hold and TCSC could not provide BCM calibrations to add or change any of the above options/ accessories.

Correction

The issue has been resolved.

Dealers can now contact TCSC for assistance with software reconfiguration for the above options/accessories.

Version	2
Modified	10/10/2025 - Created on. 01/28/2026 - to add repair information.