2025 Ontour

1.CO MONITOR BEEPS RANDOMLY CAUSE DEFECTIVE INTERNAL ISSUE CORRECTION REPLACE TIME ½ HR TO R&R.

0.30 approved plus part amount.