Service Bulletin

Bulletin No.: PIT6488
Date: February, 2026

PRELIMINARY INFORMATION

Subject: U1615 Setting In Power Steering Control Module

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024		ALL	ALL	BEV	BEV

Involved Region or Country	North America
Additional Options (RPO)	9C1, 9C3
Condition	During diagnosis of a vehicle U1615 may be found set current or in history in the K43 Power Steering Control Module
Cause	Engineering is currently investigating

Correction

U1615 set in the K43 PSCM will not cause any issues with the operation of the vehicle.

Do not replace any parts in an attempt to correct U1615.

This PI will be converted to a bulletin when a determination is made by engineering.

Version	1
Modified	02/20/2026 — Created.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION

Copyright 2026 General Motors. All Rights Reserved.