SERVICE BULLETIN

M1718 2026-02-11

M1718: 2026 FLTR MODELS WITH ADJUSTABLE WING SPOILER ASSEMBLY

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2026-02-11	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that due to a resin shortage, on **ALL FLTR Touring and Trike models** built on or after January 21, 2026, the inner side spoiler (2) of the Adjustable Wing Spoiler Assembly will be in a solid black versus translucent (see-through type material). The adjustable wing (1) of the assembly will remain translucent. See Figure 1.



1. **Adjustable wing**
2. **Inner side spoiler**

Figure 1. Adjustable Wing Spoiler Assembly

Required Dealer Action

Table 2. Required Dealer Action

Category	Description	Required
1	Must Perform Repair	☐
2	Repair If Presenting Symptom	☐

Table 2. Required Dealer Action

Category	Description	Required
3	Feature Pack- Customer/Dealer Paid	☐
4	Informational Purposes Only	☑

This is for a temporary period of approximately 10 weeks. There is no plan to service the components produced with the alternate resin.

Warrantable defects would require replacement of both Wing Assemblies using the opaque service parts (Part No. 57200375C and Part No. 57200376C).

Vehicles Affected

2026: Road Glide (FLTRX), Road Glide Limited (FLTRXL), Police Road Glide (FLTRXP), CVO Road Glide ST (FLTRXSTSE), Road Glide 3 (FLTRT)

Markets Affected

All markets affected.

Affected Part Numbers

Refer to Table 3.

Table 3. Part Numbers

Part No.	Item Description
57200375C	ASSY, SPLR, WING, ADJ, LH
57200376C	ASSY, SPLR, WING, ADJ, RH

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									