WARRANTY BULLETIN

****NON-MANDATORY****

DOCUMENT: WAR-2022-11

SUBJECT: TFT GAUGE “Insufficient Oil” Message

VEHICLE(S) AFFECTED: Early-Production MY2022 CFMOTO 300NK, 300SS, 650NK, 650 ADVentura

ISSUED: November 25, 2024

PLEASE NOTE: This warranty bulletin is intended to inform service personnel regarding factory authorized warranty repairs to CFMOTO products. No other warranty coverage applies, is implied, or is to be inferred as a result of this publication. Questions regarding this publication should be directed to CFMOTO Technical Service.

Dealer Sign-off Section – Please notify the appropriate personnel	
Sales Manager	
Warranty/Svc Manager	
Technician(s)	

ISSUE:

CFMOTO-USA is alerting motorcycle dealers that certain early-production 2022 CFMOTO 300NK, 300SS, 650NK, and 650 ADVentura motorcycle TFT gauges will display an incorrect *‘Warning - Insufficient Oil’* message that is meant to alert the operator to a low fuel condition:

- *The warning message IS NOT an indication of low engine oil.*
- The message is an incorrect translation of ‘Low Fuel’ incorporated into the gauge software.
- When the fuel level is low, the low fuel light illuminates and the warning message appears at the bottom of the display as shown:



SOLUTION:

CFMOTO-USA has issued NON-MANDATORY Warranty Bulletin **WAR-2022-11** to allow dealerships the option of sending early-production TFT gauges with an incorrect warning to CFMOTO-USA for an update to remove the ‘Warning-Insufficient Oil’ message. This bulletin should be performed if the owner has presented the vehicle with the specified complaint, or to correct unsold early-production vehicles in inventory for quality assurance.

***IMPORTANT:* Do not send TFT gauges from vehicles with VINs that do not qualify. The claim will be denied. Contact Technical Service with any questions regarding coverage.**

FOR AFFECTED VEHICLES THAT QUALIFY – SEE INFORMATION ON PAGE 2