SERVICE ACTION

Global Service Action Number: D131

Subject: **Incorrect Wheel Color and Trim Finish**	Publication No.: D131
	Model: Range Rover Velar (LY)
	Model Year: 2026
	Date of Issue: 21 July 2026
	Expiry Date: 30 April 2028

To:	The National Sales Company (NSC), importers, retailers and authorized repairers in the UK
For the Attention of:	The approved JLR retailer / authorized repairer.
Important:	NOTE: The information in this campaign is intended for use by professional technicians.If you are not a JLR retailer / authorized repairer, do not assume that a condition described affects a specific vehicle. Contact an authorized JLR retailer / authorized repairer to determine if this campaign applies to a specific vehicle. This campaign has been issued to provide the relevant repair instructions, parts and warranty information. This campaign is valid for two years only. Repairs must be completed prior to the expiry date at the top of this campaign. This bulletin supersedes Update Prior to Sale (UPS) notice UPS1926-2 with immediate effect. The blue highlighted text relates only to the date information. All text in this bulletin should be read and understood in full.

FOR THE ATTENTION OF ALL:

DESCRIPTION OF ISSUE

A concern has been identified on a small number of 2026 model year Range Rover Velar vehicles, where the wheel color and trim finish is incorrect.

The followingVehicle Identification Number (VIN)s are affected:

UK Affected VIN

- SALYA2AW6TA835512 (LY835512)

ACTION TO BE TAKEN

At the next opportunity, you are requested to repair the vehicle.

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

JLR retailers / authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.

An owner may indicate that a repair has already been completed for this concern, in which case the full cost of the repair should be reimbursed. Refer to the warranty section of this campaign for details of the Customer Reimbursement and Related Damage Process. At the time of confirming a booking for a vehicle repair, make sure you check the Warranty Portal to confirm if there are any other outstanding campaigns, to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

Yours faithfully

Steve Oldham

Global Customer Care Experience Director

SERVICE INSTRUCTION - D131

Parts Information

Parts for this campaign are being distributed to market(s) as required. You must only order parts when a confirmed repair date is set.

The parts below must be ordered through JLR in the normal manner.

Description	Part Number / Sundry	Qty / Value £
10 spoke, dark gray, diamond turned wheel	LR141891	2
Tire valve and screw kit	LR160178	2
Wheel weights	*ZZZ999	£2

*An allowance equivalent to £2 Sterling, has been allocated to locally source wheel weights.

SROs

Description	Vehicle Identification Number (VIN)	SRO	Time
Renew 2 wheels	LY835512	05.10.70	0.7

NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

Warranty Information

Warranty claims must be submitted quoting program code D131 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter SROs or parts, these are included for information only.

Program	Option	Description	VIN	SRO	Time	Part Number/Sundry	Quantity/Value £
D131	C	Renew 2 wheels	LY835512	05.10.70	0.7	LR141891 LR160178 *ZZZ999	2 2 £2
D131	D	Renew 2 wheels Drive in / drive out	LY835512	05.10.70 02.02.02	0.7 0.2	LR141891 LR160178 *ZZZ999	2 2 £2

NOTE:

The option that contains the drive in / drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.

Warranty claims must be submitted in accordance with the current JLR Global Warranty Manual, and its amendments, unless stated otherwise in this campaign.

Customer Reimbursement and Related Damage Process

NOTE:

If there is a requirement to claim for related / consequential damage or customer reimbursement, refer to the related instruction that can be found in TOPIx (in the Search box, search for 'Related Damage Claim' and open the related bulletin link).

SERVICE INSTRUCTION

NOTE:

Vehicles may have been installed with 1 or more 'Dark Satin Gray' road wheels. This is the incorrect specification for the vehicle build. 'Dark Satin Gray' road wheels must be removed and 'Gray Diamond Turned' road wheels installed.

1. Identify the road wheels that require replacement.

- 'Dark Satin Gray' road wheels, as shown in the illustration with the **RED X**, must be removed and 'Gray Diamond Turned' road wheels, as shown in the illustration with the **GREEN ✓**, installed.

E415321

2.

CAUTIONS:

- Do not renew the Tire Pressure Monitoring System (TPMS) sensor(s).
- The tire valve must be renewed.

Renew the required road wheels, (see TOPIx Workshop Manual section 204-04: Wheel and Tires - Removal and Installation - Tire Pressure Sensor).