STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

Instrument Panel Cluster (IPC) Blank XZ1 Warranty Extension

REFERENCE:	**TSB:** 08-298-26 **GROUP:** 08 - Electrical	**Date:**	July 31, 2026	**REVISION:**	—
VEHICLES AFFECTED:	**2018 - 2020 (JL) Jeep Wrangler** **2020 (JT) Jeep Gladiator** **This bulletin applies to vehicles built on or before January 01, 2020 (MDH 0101XX) and equipped with a Cluster 7.0" TFT Color Display (Sales Code JAL) or a Cluster 7.0" TFT Color Display (Sales Code JAJ).**			**MARKET APPLICABILITY:** ☒ NA ☐ MEA ☐ SA ☐ IAP ☐ EE ☐ CH **NOTE: This bulletin applies to the North America markets.**	
CUSTOMER SYMPTOM:	**Customers may experience the following:** • A blank IPC display. No information is displayed for the speedometer, fuel level, temperature gauge, odometer, outside temperature and PRNDL. **NOTE: The speedometer and tachometer continue to function normally.**				
CAUSE:	**Printed circuit board failure**				

REPAIR SUMMARY:

This bulletin involves replacing the IPC.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-45-10-9U	Cluster, Instrument Panel - Replace (2 – Skilled)	6 - Electrical and Body Systems	0.5 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	68233868AQ	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68233869AQ	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68233871AQ	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68296256AQ	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68296257AQ	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68296259AQ	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68377781AH	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68377782AH	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68377784AH	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68377798AH	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68377799AH	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68377800AH	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68442272AG	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68442273AG	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68442275AG	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68442288AG	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68442289AG	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68442290AG	Instrument Panel Cluster	Check StarParts for VIN applicability
1 (AR)	68336280AJ	Instrument Panel Cluster	Check StarParts for VIN applicability

DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the IPC. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>08 - Electrical / 8J - Instrument Cluster / Removal and Installation.

POLICY:

Warranty Extension to extend the current warranty period of 15 years/240,000 km (150,000 mi) from the vehicles in-service date. See Warranty Bulletin: Canada: SAB 2026-25 U.S.: D-26-17, PR/U.S.VI: ID-26-37 and Mexico: WE-01-26 for details associated with the Warranty Extension.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.