MAS005282 RU 26-19

RAPID UPDATE
FROM: Maserati TSO
TO: Maserati Network

Maserati
PERSONAL SERVICE LAB
MASTERS OF CARE

Rapid Update 830
Grecale – Steering Column Switch Replacement

DATE: August 6, 2026

Certain Maserati vehicles listed in MODISCS+ are involved in a Rapid Update to replace the steering column switch

VEHICLES INVOLVED: (M182) Grecale MY25

Description

Under certain high-humidity and high-temperature conditions, bubbles may be visible on the steering wheel gearshift paddles integrated into the steering column switch assembly on some vehicles. This condition does not affect functionality and is limited to the appearance of the component. This service campaign is intended to support Maserati quality standards and customer satisfaction.

Required Action

Replace the complete steering column switch following the procedure provided in this bulletin.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before ordering parts and/or starting the procedure.
Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati Americas
Aftersales Dept.

© 2026 Maserati Americas Aftersales
www.maseratiusa.com

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in USA

Technical Procedure

All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.

2. Replace the complete steering column switch following the instructions provided in the Workshop Manual.
   a. **8.50.002 STEERING COLUMN STALK ASSEMBLY Removal-Refitting or Replacement**

3. Refit the removed components in reverse order of the removal procedure.

4. Upon completion of the procedure, the vehicle may be released.

Spare Parts

To proceed with the activity, the following spare parts, which are already available in our supply chain, must be ordered.

Spare parts	PN	Qty
STEERING COLUMN SWITCH (ROW)	670325234	1
STEERING COLUMN SWITCH (NA)	670325235	1

WARNING: refer to the **VIN list below** to identify the correct part code to be ordered according to the vehicle interior trim specifications.

ZN6PMDBA7S7464296	670325234
ZN6PMDAA9S7463054	670325235
ZN6PMDAA3S7462935	670325235
ZN6PMDDC9S7464976	670325235
ZN6PMDDC0S7464977	670325235
ZN6PMDBA6S7462927	670325235
ZN6PMDBA6S7465830	670325235

Warranty Claim

Submit the warranty claim as indicated below:

Description	Code
Rapid Update number	830
Warranty code	23
Fault code	063
Component code	8.50.002
Operation code ▪ Component replacement	8.50.002.A (0,50 h)

5.

© 2026 Maserati Americas Aftersales
www.maseratiusa.com

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in USA