Service Bulletin

American Honda Motor Co., Inc.

EMISSION RECALL

2020-2026 GROM 125
FUEL SYSTEM

(This bulletin has been revised to update expected parts availability.)

NEW

BACKGROUND

Honda is launching an **EMISSION RECALL** on **ALL 2020-2026 Grom 125 motorcycles**. A fuel permeation test revealed that the fuel system does not meet regulatory standards. The fuel system has a lower than expected permeation value and is not within emission certification compliance.

AFFECTED UNITS

As of August 7, 2025, you **MUST NOT SELL ANY NEW or USED** 2020-2026 Grom 125 motorcycles until it is repaired according to forthcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on ***iN***.
- To manage your affected new inventory, use your dealer *eResponsibility Report on* ***iN***.

CUSTOMER NOTIFICATION

American Honda initially mailed customer letters to all owners of affected 2020-2026 Grom 125 in April 2026. Customers were informed that their motorcycle is affected by an emissions-related defect. Once parts become available, customers will be notified by a second letter to make an appointment with an authorized Honda dealer for repair

PARTS INFORMATION

NEW

Parts needed for the repair are currently expected in April 2027 and can be ordered according to the instructions in the forthcoming Service Bulletin. Dealers will be notified by ***iN*** message once parts become available.

SERVICE BULLETIN

GROM125 #3, which includes all the information relating to this Emission Recall, is expected to be issued in April 2027.

FLOORING SUPPORT

Due to the delayed availability of parts, American Honda will issue a prepaid flooring credit for all new, unregistered GROM125 motorcycles in dealer inventory. For details, refer to the *Quality Issue Flooring Support* bulletin #26-0050 found on the ***iN*** under Sales >Sales Bulletins.

DEALER REPAIR RESPONSIBILITY
• Repairs must be performed by a qualified technician. • Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions. • Service Management should inspect and confirm the repair. • Dealer submission of a warranty claim affirms this repair was properly performed.

© 2026 American Honda Motor Co., Inc. – All Rights Reserved

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your Honda. These procedures should not be attempted by any other individuals and you should not assume this bulletin applies to your Honda, or that your Honda has the condition described. To determine whether this information applies, contact an authorized Honda dealer.