# Service Bulletin

Bulletin No.: PIT6548

Date: September, 2026

# PRELIMINARY INFORMATION

## Subject: Doors Not Locking/Unlocking Using The Door Handle

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|---|---|---|---|---|---|---|---|
| | | from | to | from | to | | |
| Chevrolet | Equinox EV | 2026 | | All | All | All | All |

| | |
|---|---|
| **Involved Region or Country** | United States, Canada, Mexico, Middle East |
| **Condition** | A customer may notice that they cannot unlock/lock the vehicle while depressing their thumb on the square detent pad on the door handle assembly. Upon inspection, the issue may only be duplicated with outside temperatures around or above 90 degrees Fahrenheit. |
| **Cause** | Engineering is investigating. |

## Correction

Do not replace any parts. The PI will be updated or replaced with TSB once a determination has been made. In the meantime, please continue to drive your vehicle.

| | |
|---|---|
| **Version** | 1 |
| **Modified** | 09/15/2026 Created on |

**GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.**

**WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION**

*Copyright 2026 General Motors. All Rights Reserved.*