Service Bulletin

Bulletin No.: PIC6665
Date: September, 2026


PRELIMINARY INFORMATION

Subject: Paint Pealing from Front Fascia Near Headlamp

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	OPTIQ	2027		All	All	All	All

Involved Region or Country	North America
Condition	A customer may comment that the paint on the area around the head lamp of the front fascia is peeling.
Cause	Engineering is currently investigating.

Correction



7224150

Copyright 2026 General Motors. All Rights Reserved.



7224151

While engineering is investigating the issue please follow normal SI instructions to repair the vehicle.

Version	1
Modified	09/25/2026 - Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION