STELLANTIS
PARTS & SERVICES

Technical Service Bulletin (TSB)

Windshield Wiper Rattle Noise

REFERENCE:	**TSB:** 23-045-26 **GROUP:** 23 - Body	**Date:**	September 24, 2026	**REVISION:**	23-105-23
VEHICLES AFFECTED:	**2022 - 2024 (B1) Jeep Renegade** **This bulletin applies to vehicles built on or after July 10, 2022 (MDH0710XX) and on or before September 11, 2023 (MDH 0911XX).**			**MARKET APPLICABILITY:** ☐ NA ☐ CH ☐ EE ☐ IAP ☒ SA ☐ MEA **NOTE: **This bulletin applies to the South America markets.****	
CUSTOMER SYMPTOM:	**Customers may experience the following:** • Rattle Noise when the windshield wipers are active.				
CAUSE:	**Defective wipers**				

This bulletin supersedes Technical Service Bulletin (TSB) 23-105-23, date of issue October 07, 2023, which should be removed from your files. All revisions are highlighted with **asterisks and include a new Market Applicability note, Repair Procedure note, an updated Repair Summary, Labor Description, part numbers Diagnosis Statement, Repair Procedure and converting this bulletin to a TSB.**

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-282 date of issue October 07, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

REPAIR SUMMARY:

This bulletin involves replacing one or both front wiper arms and wiper blades.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-43-35-97	**Arms, Front Wiper - Replace** (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	**51978070**	Arm, Front Wiper, Left	
1 (AR)	**51978059**	Arm, Front Wiper, Right	
1 (AR)	**7089674**	Blades, Front Wiper, Both	

DIAGNOSIS:

**If the customer describes the symptom/condition above, perform the repair procedure.

REPAIR PROCEDURE:

1. Replace affected front wiper arm(s) and wiper blade(s). Refer to the detailed service procedures listed in DealerCONNECT> Service Library under: 08 - Electrical / 8R - Wipers/Washers / Arm, Front Wiper / Removal and Installation.

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.**

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.