2025 MY MachE

LED Driver Control Module B - LDCMB

LDCMB-25.EA.FA

Safety Compliance Recall 25C71
LED Driver Control Module B
To view your past software updates, or if you've had multiple updates completed recently, visit: https://www.ford.com/support/software-updates
1
LDCMB-25.EA.FA
"This software update contains the following key changes:
• On your vehicle, the LDCM may experience a fault, resulting in an inoperative high beam, low beam, daytime running lamp, and turn signal in that headlamp assembly. You will receive an “Advanced Front Lighting Feature Temporarily Unavailable” warning message and your turn signal indicator will flash at an increased rate (“fast flash”) in the instrument panel cluster if this occurs. Inoperative lighting features may reduce your visibility and/or make your vehicle less visible to other drivers, increasing the risk of a crash. We have updated your vehicle’s Light Emitting Diode (LED) Driver Control Module (LDCM). This completes Safety Recall 25C71. No further action is required."