Form Approved: OMB No. 2127-0001

U.S. Department of Transportation
National Highway Traffic Safety Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: http://www.nhtsa.dot.gov

FOR AGENCY USE ONLY 920

Date Received: 11-MAY-2001

Od_or ____ ____
rt_dt ____ ____
od_rt ____ ____
up_ltr ____ ____

Reference No. 888006

[redacted]

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ *YES* ☐ *NO*
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ **Date**____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Readin
1FAFP52UXWG235093	FORD	TAURUS	1998	

Purchase Dat: ☐ New ☒ Used

Dealer's Name_____ City_____ State_____ Zip Code_____

Engine Size (CID/CC/L ____ No Cylinders _____

☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injectio

Transmission Type	Antilock Brakes	Restraint System	Cruise Contro	Drive Trai	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☒ Yes ☐ No	☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	☒ Yes ☐ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other_____	☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other_____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component	Part Name(s	Location	Failed Part(s	
06136000	FUEL:FUEL PUMP	☐ Left ☐ Right ☐ Front ☐ Rear	☐ Original ☐ Replacement	

No of Failure	Date(s) of Failure(s) / Mileage at Failure(s)	Failed Part(s)	NHTSA Previously
2	01-MAR-2000 60000	☐ Yes ☐ No	☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash	Fire	Number of Persons Injured	Number of Fatalitie	Estimated Property Damag	Reported to Polic
☐ Yes ☒ No	☐ Yes ☒ No	0	0		☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

FUEL PUMP HAS FAILED TWICE, AND WAS REPLACED MARCH 2000 AND 2001. LATEST INCIDENT WAS DUE TO PUMP NOT HAVING ENOUGH PRESSURE TO PUMP FUEL INTO ENGINE. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.