

February 22, 2011

March 1, 2011

Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
1200 New Jersey Avenue, SE
Washington, DC 20590

Subject: Foreign Recall Information Report
1998-2004MY Isuzu Big Horn, Wizard, MU, Trooper, Opel Monterey, Holden Monterey,
Holden Jackaroo and Honda Horizon

On behalf of Isuzu Motors Limited ("IML"), pursuant to 49 CFR §579.12, Isuzu Manufacturing Services of America, Inc. (collectively "Isuzu") hereby submits a Foreign Recall Information Report concerning the foreign noncompliance recall campaign of certain 1998-2004MY Isuzu Big Horn, Wizard, MU, Trooper, Opel Monterey, Holden Monterey, Holden Jackaroo and Honda Horizon light-duty vehicles sold in Japan and other countries (hereinafter, the "subject vehicles" or the "affected vehicles").

Please see attachment for vehicle build locations.

573.6 (c)(1)

Manufacturer: Isuzu Motors Limited
26-1, Minami-ooi 6-chome
Shinagawa-ku, Tokyo 140-8722 Japan

Supplier: Delphi Automotive Systems Japan, Ltd.
1-24-13 Asahi-cho, Atsugi-shi, Kanagawa-ken, 243-0014, Japan
Tel: +81-46-400-4732

573.6 (c)(2):

The subject vehicles sold in Japan and other countries are substantially similar (as "substantially similar" is defined in 49 CFR Section 579.4) to certain Isuzu Trooper, Isuzu Rodeo, Isuzu Amigo, Isuzu Rodeo Sport, Honda Acura SLX and Honda Passport vehicles sold in the United States. However, the affected vehicle models sold in Japan and the other countries were built with a diesel engine with different wiring connections than used in the gasoline engine-equipped vehicle models sold in U.S., and no vehicles with the affected engines were sold in the U.S. Nonetheless, in an abundance of caution and in recognition of the goals of the NHTSA reporting requirements, Isuzu is filing this report to ensure that the Agency is aware of this recall.

573.6 (c)(3)

Please see Attachment 1.

573.6 (c)(5):

Summary:


Due to an insufficient connection between the wire harness and accelerator control sensor, the resistance of the connector is increased, thereby causing the possibility of increased output voltage and intermittent increases in engine speed.

Detailed description:

After receiving some complaints from owners of affected vehicles sold in Japan about intermittent engine speed increases noticed while the vehicles were at a stop, IML started to conduct an investigation. In the end, IML determined that an insufficient connection between the wire harness and accelerator control sensor in the diesel engine-equipped vehicles sold in Japan and other countries could cause increased resistance. When that occurs, output voltage will be increased and potentially can cause intermittent engine speed increases.

If you have any questions or require additional information, please contact me at 734-582-9262 or Scott Crafard of my staff at 734-582-9250.

Sincerely,

A handwritten signature in dark ink, appearing to read 'Jeffery A. Marsee', with a stylized flourish extending to the right.

Jeffery A. Marsee
Chief Representative
Emissions and Safety
Isuzu Manufacturing Services of America, Inc

Enclosure

Attachment 1 §573.6(c)(3) and 579.12

Country	Model Series	Model Year ¹	Number Involved	Inclusive Manufacturing Dates
Japan	Isuzu Big Horn	1998-2002	9,448 units	February, 1998 ~ March, 2002
Japan	Honda Horizon	1998-2001	66 units	February, 1998 ~ March, 2002
Japan	Isuzu Wizard	1998-2001	6,939 units	March, 1998 ~ October, 2001
Japan	Isuzu MU	1998-2001	734 units	March, 1998 ~ May, 2001
Asia, Oceania, Europe, Africa and Central & South America	Isuzu Trooper Opel Monterey , Holden Monterey Holden Jackaroo	1998-2004	Approx. 49,000 units	April, 1997 ~ July, 2004

Safety Recall or Safety Campaign	Determination made by	Date of Determination	Date the Campaign Commenced	Description of Program	Substantially similar ² vehicles produced during the same period as the affected vehicles
Recall Campaign (Japan)	Manufacturer	February 16, 2011	February 18, 2011 (Japan)	For all the subject vehicles, the wiring will be modified to improve the connection and reduce the potential for increased electrical resistance	Isuzu Trooper, Rodeo, Amigo, Rodeo Sport, Honda Acura, Passport

¹ In Japan, model years can last for multiple calendar years. Manufacture year is reported as MY in this report.

² The vehicles are “substantially similarly” insofar as that term is defined in 49 CFR Section 579.4.

Vehicle build locations

Subject Vehicle	Substantially Similar Vehicle	Manufacture/Assembled Location
Isuzu Big Horn, Honda Horizon Isuzu Trooper, Opel Monterey , Holden Monterey, Holden Jackaroo	Isuzu Trooper Honda Acura SLX	Isuzu, Fujisawa, Japan
Isuzu Wizard	Isuzu Rodeo Honda Passport	SIA, Lafayette, IN, USA
Isuzu MU	Isuzu Amigo Isuzu Rodeo Sport	SIA, Lafayette, IN, USA