



ETON America, LLC.
7092 Howard Street, Unit - F
Spartanburg, SC 29303

Phone 866-224-3318 x200 Customer Srv
Phone 866-224-3319 x114 Tech Srv.
Fax 864-278-9590



E-Mail info@etonamerica.com

March 7, 2007

AAA Motorsports ET0113
8427 Bird Rd (SW 40th)
Miami, FL 33155

2005 Beamer II and Beamer Matrix Recall

Dear AAA Motorsports,

E-TON has determine that certain 2005 E-TON Beamers and Beamer Matrix Scooters may develop stress cracks on the rear wheel in the area of the brake drum attachment.

E-TON is voluntarily recalling these units and requesting you to replace the rear wheel and tire assembly on these units per the instructions on the enclosed Service Bulletin #SB-0050.

Also enclose is a list of the affected unit which have been shipped to your store along with the owner registration information of each unit. Replacement rear wheels and tire assemblies are being shipped to your store to perform this replacement. As you replace the rear wheel and tire assembly please sign and date the enclosed Warranty Claim Form and when all replacement have been completed return this form to ETON America and a warranty credit will be issued to your account for the total allotted time for this replacement. The replaced rear wheels are to be discarded and not returned to ETON America.

Each registered owner has been notified by First Class letter of this recall.

Sincerely,

ETON America
Quality Assurance Department

Encl; Service Bulletin #SB-0050, Affected VIN list/Warranty Claim Form.



ETON America, LLC



Service Bulletin

Bulletin No:	0050
Date:	03/01/2007

Beamer rear wheel inspection and removal.

Put the bike on the center stand and let the exhaust cool down before installation . Then remove the (2) 10mm bolts from the exhaust pipe flange on the bottom of the cylinder. The remove the (2) 12mm bolts from the exhaust RH side. Once the exhaust is removed then, remove the 24mm wheel nut and washer. Remove the wheel and replace with a new factory wheel and rim.

