INTERACTIVE NETWORK

Sent on	08 06 2014 **Expires on** 11 03 2014
From	Acura Parts, Service & Technical Division, Campaign Administration
Subject	2002-06 Multi-Model Airbag Inflator Recalls SALES & SERVICE UPDATE

DATE: August 6, 2014

TO: All Acura Service Managers and Personnel
FROM: Acura Parts, Service & Technical Division, Campaign Administration

RE: 2001-11 Multi-Model Airbag Inflator Recalls **SALES & SERVICE UPDATE**

On Monday, June 23, 2014, Acura announced three recalls for various 2002-06 Acura models. As of August 4, 2014, affected VINs have been identified, and VIN status inquiry has been updated.

VIN status inquiry will now refer to one or more of the following bulletins:

- 14-023, *Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized,*
- 14-029, *Recall: Front Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity*
- 14-030, *Recall: Front Passenger's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity*

Vehicles visiting the dealership for service
Follow the directions listed in the service bulletin(s) to ensure proper handling of these affected units. Vehicles that do not display VIN status inquiry links to any of the bulletins listed above do not require additional action related to these campaigns.

Vehicles available for sale in dealer inventory
The sales disclosure form procedure is still required for unsold units; please continue to use this form until otherwise advised by Acura. Vehicles that do not display VIN status inquiry links to any of the bulletins listed above do not require any additional disclosure prior to sale.

Please click here for an updated copy of the Sales disclosure form.

Parts to support this issue remain unavailable at this time. Acura will notify you once additional information is available regarding this situation.

ⒶACURA

AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., P.O. Box 2215
Torrance, CA 90509-9870

AIRBAG INFLATOR RECALL DISCLOSURE & ACKNOWLEDGMENT

DEALER NAME: _____ DEALER NO.: _____ DATE: _____

VIN: ☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐ MODEL YEAR/MODEL: _____

NAME: _____

STREET ADDRESS: _____ APT./SUITE: _____

CITY: _____ STATE: _____ ZIP: _____

PHONE: _____ EMAIL: _____

REGISTERED OWNER? Y / N

IF NO, REGISTERED OWNER NAME: _____

STREET ADDRESS: _____ APT./SUITE: _____

CITY: _____ STATE: _____ ZIP: _____

PHONE: _____ EMAIL: _____

I, the above named individual, acknowledge that the above named dealer, on behalf of itself and American Honda Motor Co., Inc. (and their various affiliates), advised me that the vehicle identified above is subject to one or more recalls affecting the driver's or passenger's front airbag inflators (or both) and the affected airbag inflator(s) were not replaced prior to its sale to me. I was further informed the vehicle did not receive the recall repair(s) because the parts necessary to complete the recall repair are not yet available and may not become available for a period of months. I further acknowledge I was advised the recall(s) are being conducted as it is possible that in a crash the front airbag inflator(s) in affected vehicles may deploy with too much pressure, causing the inflator casing to rupture and shoot out metal fragments. If struck with these metal fragments, a vehicle occupant could be injured or killed.

SIGNATURE: _____

Model	Model Year(s), Airbag D=Driver's, P=Passenger's:
CL	02-03 (D)
MDX	03-06 (D), 03-05 (P)
RL	05 (P)
TL	02-03 (D)