

Part 573 Safety Recall Report

16V-512

Manufacturer Name : Newmar Corporation

Submission Date : JUL 05, 2016

NHTSA Recall No. : 16V-512

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 77

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

Production Dates : DEC 04, 2015 - JUL 05, 2016

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 2 : 2017-2017 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

Production Dates : DEC 04, 2015 - JUL 05, 2016

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 3 : 2017-2017 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

Production Dates : DEC 04, 2015 - JUL 05, 2016

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2017-2017 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

Production Dates : DEC 04, 2015 - JUL 05, 2016

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 5 : 2017-2017 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

Production Dates : DEC 04, 2015 - JUL 05, 2016

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : On Certain motorhomes manufactured by Newmar Corporation, the front fascia wood trim has the potential to separate from the slide out. If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or

injury/damage. Correction: Newmar will secure the fascia trim to the slide out.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the fascia trim separates from the slide out it could possibly make contact with the driver or passenger causing loss of control of the vehicle resulting in a crash or injury/damage.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Newmar was made aware of the possibility of the potential defect in June 2016. July 2016 Newmar gave notice of defect for the loose fascia trim.

Description of Remedy :

Description of Remedy Program : Newmar will use screws to secure the trim at no cost to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 03, 2016 - SEP 03, 2016

Planned Owner Notification Date : SEP 03, 2016 - SEP 03, 2016

* NR - Not Reported