

Part 573 Safety Recall Report

25E-011

Manufacturer Name : MORryde International, Inc.

Submission Date : FEB 21, 2025

NHTSA Recall No. : 25E-011

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : MORryde International, Inc.

Address : 1966 Sterling Avenue
Elkhart IN 46516

Company phone : (574) 293-1581

Population :

Number of potentially involved : 72

Estimated percentage with defect : 100 %

Equipment Information :

Brand / Trade 1 : Grand Design Serenova

Model : 150HL / 160LG

Part No. : IST22-008

Size : NR

Function : NR

Descriptive Information : Recalling full population of IST22-008 installed on Grand Design Serenova's that have not been previously inspected/repaired. Product not recalled have bearings properly torqued.

Production Dates : SEP 04, 2024 - JAN 28, 2025

Description of Defect :

Description of the Defect : The nut that retains the bearings was installed too tight, which put added pressure on the bearings and could cause the bearing to overheat.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the bearing overheats, the bearing grease could burn causing the bearings not to work properly. In this event, the tire could disconnect from the travel trailer.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name : bearings

Component Description : bearings

Component Part Number : IST22-008

Supplier Identification :

Component Manufacturer

Name : MORryde International, Inc.

Address : 1966 Sterling Avenue
Elkhart Indiana 46516

Country : United States

Chronology :

1/28/2025 – notice of tire disconnecting from travel trailer - warranty claim submitted from Grand Design to MORryde.

1/30/2025 through 2/5/2025 – inspected units at Grand Design

2/10/2025 – Safety Committee met and voted to issue a safety recall.

We had 1 warranty claim, no injuries, no deaths.

Description of Remedy :

Description of Remedy Program : Inspect the bearings to visually see if the grease has started to burn. If not, adjust the nut. If evidence of burning, repair is needed. See inspection and repair instructions. If failed, MORryde will replace failed parts, free of charge under warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : 2/14/2025, implemented a new process with automated tools to set the torque of the axle bearing nuts automatically

Recall Schedule :

Description of Recall Schedule : MORryde has no dealer network. Notified Grand Design of recall 2/14/2025. Grand Design will be notifying customers and reporting quarterly due to not having end user customers.

Planned Dealer Notification Date : FEB 14, 2025 - MAR 14, 2025

Planned Owner Notification Date : MAR 03, 2025 - MAR 03, 2025

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported