



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V646

Manufacturer Name: Forest River, Inc.

Submission Date: Oct 05, 2026

NHTSA Recall No.: 26V646

Manufacturer Recall No.: 34-2102

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 75

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2027 FOREST RIVER SUNSEEKER

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: Oct 30, 2025 - Sep 03, 2026

Number of potentially involved: 44

Descriptive Information:

The scope was determined using production records of when the chassis upfitter substituted the tires on the front axle for a short period of time due to a tire shortage.

Vehicle 2: 2026-2027 FOREST RIVER SOLERA

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: Jan 29, 2026 - Aug 10, 2026

Number of potentially involved: 10

Descriptive Information:

The scope was determined using production records of when the chassis upfitter substituted the tires on the front axle for a short period of time due to a tire shortage.

Vehicle 3: 2026-2027 FOREST RIVER FORESTER

Part 573 Safety Recall Report

26V646**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** Recreational Vehicle**Fuel / Propulsion:****Production Dates:** Dec 23, 2025 - Sep 09, 2026**Number of potentially involved:** 21**Descriptive Information:**

The scope was determined using production records of when the chassis upfitter substituted the tires on the front axle for a short period of time due to a tire shortage.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The Federal Placard indicated the front tire to receive 80PSI, whereas the front tire is only capable of 65PSI.

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

An over-inflated tire may lead to tire failure, loss of control, resulting in a crash.

Description of the cause:

Manufacturing Error

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:****Address:****Country:**

Part 573 Safety Recall Report

26V646

Involved Components

Component Name 1: FEDERAL PLACARD

Component Description: FEDERAL PLACARD

Component Part Number: FEDERAL PLACARD

Chronology

On September 29, 2026, Forest River's Office of Corporate Compliance ("OCC") was notified of a matter in which the Federal Placards on specific serials assigned a 265/65 R17 tire at 80PSI instead of the tires' maximum PSI rating of 65PSI. OCC opened a research item into the matter.

On October 2, 2026, OCC identified vehicles had shipped into commerce.

On October 5, 2026, Forest River's Corporate Committee voted to Recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to replace the Federal Placard with the correct PSI listed.

What is the Forest River Customer Service Phone Number? 574-206-7600

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Forest River Class Cs
Forest River, Inc.
Attn: WARRANTY MANAGER
914 CR 1
Elkhart, IN 46514

Part 573 Safety Recall Report

26V646**How remedy component differs from recalled component:**

Federal Placard now indicates the correct PSI for tires on the vehicles.

Identify how/when recall condition was corrected in production:

Due to a tire shortage, the chassis upfitter needed to substitute the front tires for a short period. Once the normal tires were in place again, the upfitter switched back to the appropriate tire.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Dec 04, 2026 - Dec 04, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Dec 04, 2026 - Dec 04, 2026

☐ Phased Recall

Date when VIN will be searchable: