



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V647

Manufacturer Name: Forest River, Inc.

Submission Date: Oct 05, 2026

NHTSA Recall No.: 26V647

Manufacturer Recall No.: 37-2103

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 5

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2027-2027 FOREST RIVER SURVEYOR

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Sep 18, 2026 - Sep 18, 2026

Number of potentially involved: 5

Descriptive Information:

The scope was identified since inception of the new model to current date.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The exterior receptacle may not be wired on the GFCI circuit.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A non-GFCI protected exterior receptacle may lead to electrical shock and personal injury.

Description of the cause:

Part 573 Safety Recall Report

26V647

Manufacturing Error.

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: GFCI receptacle

Component Description: GFCI receptacle

Component Part Number: GFCI receptacle

Chronology

On September 30, 2026, Forest River's Office of Corporate Compliance ("OCC") was notified by the manufacturing plant of the matter. OCC opened research.

On October 5, 2026, Forest River's corporate committee voted to Recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Part 573 Safety Recall Report

26V647

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to re-wire the exterior receptacle to the GFCI circuit.

What is the Forest River Customer Service Phone Number? 574-642-3119

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Surveyor
Forest River, Inc.
Attn: WARRANTY MANAGER
2405 Century Dr
Goshen, IN 46528

How remedy component differs from recalled component:

The exterior receptacle will be wired correctly to the GFCI circuit.

Identify how/when recall condition was corrected in production:

The manufacturing plant began wiring the exterior receptacle to the GFCI circuit the week of September 28, 2026, on all affected units in Forest River's control.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Dec 04, 2026 - Dec 04, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☒ No Owners

Planned Remedy Owner Notification Date:

☐ Phased Recall

Date when VIN will be searchable: