



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V666

Manufacturer Name: Altec Industries, Inc.

Submission Date: Oct 09, 2026

NHTSA Recall No.: 26V666

Manufacturer Recall No.: CSN-3376

Manufacturer Information

Population

Manufacturer Name: Altec Industries, Inc.

Address: 210 Inverness Center Drive
Birmingham AL, 35242

Total number of potentially involved: 1,053

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 ALTEC AC SERIES CRANE

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Truck

Fuel / Propulsion:

Production Dates: Mar 02, 2026 - Aug 03, 2026

Number of potentially involved: 1

Descriptive Information:

The recall population was determined from a review of production records.

Vehicle 2: 2026-2026 ALTEC SERVICE BODY

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Mar 02, 2026 - Aug 03, 2026

Number of potentially involved: 12

Descriptive Information:

The recall population was determined from a review of production records.

Vehicle 3: 2026-2026 ALTEC DIGGER DERRICK

Product Category: Buses, Medium & Heavy Vehicles

Part 573 Safety Recall Report

26V666**Product Type:** Truck**Fuel / Propulsion:****Production Dates:** Mar 02, 2026 - Aug 03, 2026**Number of potentially involved:** 370**Descriptive Information:**

The recall population was determined from a review of production records.

Vehicle 4: 2026-2026 ALTEC AERIAL DEVICE**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:** Truck**Fuel / Propulsion:****Production Dates:** Mar 03, 2026 - Aug 03, 2026**Number of potentially involved:** 670**Descriptive Information:**

The recall population was determined from a review of production records.

Defect / Noncompliance Description

Description of the defect or noncompliance:

During final-stage assembly, Altec removed the OEM-installed backup cameras to install Altec components. Although the cameras were included in the owners' selected chassis option packages, they were not reinstalled before the completed vehicles were shipped to the owners.

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

If a vehicle was completed without the selected backup camera, it would not meet the owner's specifications and could reduce the driver's visibility while backing, increasing the risk of a crash.

Description of the cause:**Identification of any warning that can occur:**

Part 573 Safety Recall Report

26V666

The dash-mounted monitor would display a message indicating that the backup camera was not connected.

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:** Altec**Address:** 2106 South Riverside Road
St. Joseph MO, 64507**Country:** United States

Involved Components

Component Name 1: Backup Camera**Component Description:** Backup Camera**Component Part Number:** A66-33323-000

Chronology

On August 3, 2026, Altec identified units that were shipped without the backup camera installed. A root cause investigation was initiated to determine the cause and scope of the issue. On September 8, 2026, after finding that some units might have shipped to owners without backup cameras a potential field action investigation was opened to determine if units could have been shipped to owners with backup cameras and to review the expectations for the specific vehicles to have functioning backup cameras installed. On October 2, 2026, after reviewing the production records and the potential risk to owners if the backup camera was missing on a vehicle ordered with a backup camera, Altec determined that owner notification was necessary and an Altec Product Notice would be issued to owners. There were no other warranty claims or field reports identified. There have been no accidents, injuries or deaths related to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Repair

Part 573 Safety Recall Report

26V666**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

Altec will inform the owners to inspect the vehicle for the missing backup camera. If the backup camera is not installed the owner can order and install the camera kit free of charge or schedule a repair with an Altec Service Center for the update. The recall remedy will be completed free of charge when presented for repair. The Altec Warranty Policy covers the recall remedy including cases requiring reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

How remedy component differs from recalled component:

The remedy will install the missing backup camera.

Identify how/when recall condition was corrected in production:

On October 1, 2026, after identifying that vehicles had been shipped without the backup cameras reinstalled, Altec updated its production work instructions and audit processes to prevent recurrence.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Altec will issue CSN-3376 to the owners of the affected units. Altec does not have a dealer network and issues letters to owners only.

Planned Dealer Notification Date:☒ No Dealers**Planned Interim Owner Notification Date:**☐ No Owners**Planned Remedy Owner Notification Date:** Dec 04, 2026 - Dec 04, 2026 ☐ Phased Recall**Date when VIN will be searchable:**