IMPORTANT SAFETY RECALL

FOREST RIVER

DEPARTMENT OF COMPLIANCE
VEHICLE SAFETY AND RECALL MANAGEMENT
PO Box 30
MIDDLEBURY, INDIANA 46540-9218

NHTSA RECALL: 26V609
FOREST RIVER ID: 55-2099
SERVICE CAMPAIGN: 001318

<<DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- *Integrity*
- *Safety*
- *Quality*
- *Customer Service*

October 2026

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

"It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law."
–Forest River motorized and towable products are contained in this section-

Forest River has decided that a safety defect exists in certain 2026 through 2027 Dynamax Isata Motorhome Recreational Vehicles. Forest River is recalling the defect model(s) to ensure the safety of our future retail consumers and your dealership. Forest River apologizes for any inconvenience this action may cause your dealership; however, safety, continued satisfaction, and our commitment to building great products are of the utmost importance to Forest River.

The designated Date range of production is 2/26/2026 through 7/31/2026.

DEFECT/NONCOMPLIANCE:
Ladder brackets may be secured to raw edge of plywood or OSB and may fail to hold the ladder in place.

EVALUATION OF RISK:
Ladder could pull away from bunk possibly causing injury.

SERVICE PROCEDURE:
Dealership Service Department procedures for addressing replacing the bunk mattress insert with the proper metal frame insert for the ladder bracket to secure to can be found on Dealer Connect. Enter the Service Campaign number referenced above in the "Campaign Search" field, click on the "Campaign ID Number". Next, click on "Documents" and select the Remedy Instructions.

WHAT IS THE PART NUMBER OF THE REMEDY KIT?
BUNK MAT INSERT SENT FROM PLANT WILL DEPEND ON MODEL

ISATA 3 - DYNC00082-GS
ISATA 3 24TWM - DYNBM3176-GD (ONLY SUBMODEL WITH DIFFERENT PART NUMBER)
ISATA 5 - DYNCO0083-GD—79x51
ISATA 6 - DYNCO0084-GD—79x53

DEALER REPAIR CODES: Dealer Connect

UNITED STATES	REPAIR CODE	DESCRIPTION	ALLOWABLE HOUR(S)
26V609	RC-090-05-00-004864	Inspection	.20 HRS
26V609	RC-090-01-00-004865	Repair	.50 HRS

HELPFUL CONTACT INFORMATION:

CONTACT	PHONE
CUSTOMER SERVICE	(574) 262-3474

IMPORTANT SAFETY RECALL

The Recall shall be considered the utmost priority to remedy the 2026 through 2027 Dynamax Isata Motorhome Recreational Vehicles in question. **The retail consumer shall not be charged** any amount of monies for remedy to their 2026 through 2027 Dynamax Isata Motorhome Recreational Vehicles listed under this Recall.

If your dealership has already performed the remedy to 2026 through 2027 Dynamax Isata Motorhome Recreational Vehicles, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s). If the remedy needs to be performed on an out of warranty 2026 through 2027 Dynamax Isata Motorhome Recreational Vehicles in which the VIN falls under as stated in the identified VIN listing, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s).

Notice:
In no manner shall a Forest River Product Owner or Coachmen Product Owner be charged any fee(s) for scheduling, conduction or completion of the recall. Additionally, all dealership(s) that are Forest River and/or Coachmen dealership(s) are Federally Mandated to perform the recall once presented with this recall whether by the Owner or Dealership receipt of this letter, without denial of service to the Owner. Lastly, denial of a remedy for this recall is a Federal Violation punishable by law resulting substantial fines and/or civil penalties.

Federal Regulation requires that any lessor receiving this Recall must forward a copy of this notice to the lessee within ten days. If your dealership no longer owns this vehicle, please inform the Warranty Manager of the product listed above of the change of ownership.

Sincerely,
Forest River
Office of Corporate Compliance