

## WC44 - Replacing Cage With Float (Workshop Campaign)

Vehicle Type: **Boxster (981)/Boxster S (981)**

Model Year: **2013**

Concerns: **Cage with float in coolant filler neck on service tray.**

Information: This is to inform you of a voluntary Workshop Campaign on the above-mentioned vehicles. There is the possibility that the float in the coolant filler neck is not designed correctly on the affected vehicles. As a result, the coolant level is not displayed correctly when adding coolant.

Action Required: Replace cage with float in coolant filler neck on service tray.

Affected Vehicles: The VIN(s) can be checked by using PIWIS Vehicle Information link to verify if the campaign affects the vehicle. This Campaign is scope specific to the VIN! Failure to verify in PIWIS may result in an improper repair. This campaign affects 1,172 vehicles in North America.

Parts Info: **DO NOT ORDER PARTS FOR THIS CAMPAIGN. THEY WILL BE AUTOMATICALLY ALLOCATED TO YOUR DEALERSHIP.**

981.106.155.00 ⇒ Cage with float 1

Tools: Slotted screwdriver, blade width approx. 2 mm

Work Procedure: See Attachment "A".

Claim Submission: See Attachment "B".

Attachment "A": **Work Procedure**

1 Open the rear lid.



**WARNING**

**Hot fluid**

- **Danger of scalding**


- ⇒ **Let the fluid cool down.**
- ⇒ **Wear personal protective gear.**

- 2 Open cap on coolant filler neck in the rear luggage compartment and remove it ⇒ *Cap on coolant filler neck in luggage compartment -1-*.



*Cap on coolant filler neck in luggage compartment*

- 3 Remove cage with float from the coolant filler neck.
  - 3.1 Insert a screwdriver into the cage ⇒ *Removing cage with float -1-* to the left of the red display head on the float ⇒ *Removing cage with float -2-* and guide it into the gap between the two ribs of the cage ⇒ *Removing cage with float -arrow-*. Then bend the ribs in slightly ⇒ *Removing cage with float -3-* in order to pull the ribs of the cage over the locking lug on the coolant filler neck.  
(The position of the screwdriver is shown on the removed cage for reasons of clarity.)
  - 3.2 Lift the cage together with the float up out of the coolant filler neck.




*Removing cage with float*



#### Information


The **new** cage with float, Part No. 981.106.155.00, has a **marking** on the lower edge of the cage ⇒ *New cage with marking -1-*.



*New cage with marking*

#### 4 **Install new** cage with float, Part No. **981.106.155.00**, in the coolant filler neck.

- 4.1 Position the cage so that the float can be guided into the opening on the coolant filler neck and the locking lug on the coolant filler neck ⇒ *Installing cage with float -1-* engages in the gap between the ribs of the cage directly to the left of the red display head on the float ⇒ *Installing cage with float -2-* (⇒ *Installing cage with float -arrow-*).
- 4.2 Press cage with float into the coolant filler neck and check that it is seated securely.
- 4.3 Check that the float can move freely. To do this, pull up the float at the red display head ⇒ *Installing cage with float -2-* and check that it can move freely.



*Installing cage with float*

- 5 Fit cap on the coolant filler neck and screw it in ⇒  
*Cap on coolant filler neck in luggage compartment*  
**-1-**.
- 6 Close the rear lid.
- 7 Enter the workshop campaign in the Warranty and Maintenance booklet.



*Cap on coolant filler neck in  
luggage compartment*

Attachment "B": **Claim Submission** - Workshop Campaign WC44

Warranty claims should be submitted via WWS/PQIS.

Open campaigns may be checked by using either the PIWIS Vehicle Information system or through PQIS Job Creation.

Labor, parts, and sublet will be automatically inserted when Technician is selected in WWS/PQIS. If necessary, the required part numbers will need to be manually entered into warranty system by the dealer administrator.

**Replacing cage with float in coolant filler neck.**

**Working time:**

Replacing cage with float

Labor time: **7 TU**

**Parts required:**

981.106.155.00 Cage with float

1

⇒ **Damage code WC44 066 000 2**

**Important Notice:** Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

© Porsche Cars North America, Inc.

|              |                 |                 |                    |
|--------------|-----------------|-----------------|--------------------|
| Dealership   | Service Manager | Shop Foreman    | Service Technician |
| Distribution | Asst. Manager   | Warranty Admin. | Service Technician |
| Routing      |                 |                 |                    |

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman™, Panamera®, Tiptronic®, VarioCam®, PCM®, 911®, 4S®, FOUR, UNCOMPROMISED.® and the model numbers and distinctive shapes of Porsche's automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Some vehicles may be shown with non-U.S. equipment. Porsche recommends seat belt usage and observance of traffic laws at all times.

Printed in the USA