

Audi ElsaWeb Newsletter

Edition 9: October 29, 2012

Content

- [ElsaWeb User's Guide](#)
- [Feedback Corner](#)
- [Technical Bulletins](#)
- [Campaigns](#)
- [Updates](#)
- [Repair Manuals](#)
- [Wiring Diagrams](#)
- [Suggestions](#)



ElsaWeb User's Guide

An improved Volkswagen ElsaWeb User's Guide is now available. The Guide provides up-to-date ElsaWeb content and is now available in HTML format for faster loading and enhanced navigation. To launch the Guide from ElsaWeb, click the "Help" tab, and then click the "Help Contents/Index" link.

Feedback Corner

This week's feedback is from Chris, regarding a 2013 Q7 Repair Manual. He stated:

"Repair instructions for removal and installation of the high pressure fuel pump are missing for 2013 Q7 TDI vehicles (engine CNRB). It's available on the older model (MY2012 or earlier) under "Fuel Injection and Glow Plug" under "Engine" in the repair manual."

The Service Information Team reviewed this feedback and fixed the repair manual to include the information. Chris included his full name and email address with the feedback and will receive Audi Winner's Circle Rewards for helping improve the quality of the repair information.

Feedback Status		
New	Completed	To Factory
15	15	8

*Please note that this feedback feature is not the place to obtain technical assistance for Audi vehicles, or to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create an Audi Technical Assistance ticket and contact the Audi Technical Assistance at (800)-678-2389.

[Back to top](#)

Technical Bulletins

No new Technical Bulletins.

Campaigns

24U8 - Engine Wiring Harness Overlay & ECM Programming					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
R8	2011-2012	All	All	WUA_AFG_BN000132	WUA_AFG_CN002527
R8 Spyder	2011-2012	All	All	WUA_AFG_BN000134	WUA_AFG_CN002651
Under certain driving conditions the MIL may come on even though the vehicle is operating correctly. If the MIL is on because of this issue, your vehicle may not pass an IM (emissions) inspection.					

37G6 - ECM/TCM Software/Sunroof Wind Deflector					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
A8	2011	All	All	WAU_VAFD_BN000559	WAU_VAFD_BN028395
This action is to help address the following customer satisfaction issues: - Some customers have expressed dissatisfaction with the shift quality of the transmission in their vehicle while moving from a stop, between gears, or at low speeds. - On some vehicles, there may be an issue with the sunroof wind deflector that can cause the sunroof to be noisy while driving, or in some cases it may not close.					

[Back to top](#)

Updates

No new Updates.

[Back to top](#)

Repair Manuals

Repair Manuals			
Elsa Name	Model	Book Updated	Reason
4G2	A6 Sedan 2012>	Electrical Equipment(CAEB,CGXB,CTUA)	Feedback# 626118
4F	A6 2005-2011	Fuel Injection and Ignition(CCAA)	Feedback# 631789
422,423,429	R8 2008>	Fuel Injection and Ignition(BUJ,CMPA)	Feedback# 626151
8N	TT 2000-2006	Heating, Ventilation and Air Conditioning	Feedback# 552746
4H2,4H8	A8 2011>	Suspension, Wheels, Steering	Correction
422,423,427,429	R8 2008>	Fuel Supply System Fuel Injection and Ignition Engine Mechanical	Correction
8P	A3 2006>	Fuel Injection and Glow Plug(CBEA)	Feedback# 637900

[Back to top](#)

Wiring Diagrams

Repair Manuals		
Elsa Name	Model	Book Updated
4G2,4G5,4GH,4X8	A6 2012>	Component Locations: Relay Component Locations: Fuses Component Locations: Control modules - Vehicle rear

		Component Locations: Control modules - Vehicle front Component Locations: Connector Stations and Connections
4GA	A7 2012>	Component Locations: Relay Component Locations: Fuses Component Locations: Control modules - Vehicle rear Component Locations: Control modules - Vehicle front Component Locations: Connector Stations and Connections
8F	A5,S5 Cab 2010>	Component Locations: Relays Component Locations: Fuses
8J	TT 2008>	Component Locations: Relays Component Locations: Fuses
8P1,8PA	A3 2006>	2.0L gasoline engine, BPY, from model year 2005
8R	Q5 2009>	Component Locations: Fuses
8T	A5,S5 Coupe 2008>	Component Locations: Relays Component Locations: Fuses

[Back to top](#)

Suggestions:

Please send comments or suggestions to: aoa.WorkshopInformation@audi.com

[Back to top](#)

© 2012 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.