



Service Bulletin

PRELIMINARY INFORMATION

Subject: Folding Top #5 Bow Replacement

Models: 2011 - 2013 Camaro Convertible

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A dealer may be ordering a 5 bow and see a note in the Electronic Parts Catalog (EPC) that says:

"If vehicle built on/before VIN 2G1FL3DP0D9801462, order T/W both LH 22788893 & RH 22788896 Main Pivot Brackets. If built after no need to order brackets."

Recommendation/Instructions

Please disregard this EPC note. The brackets currently do NOT need to be replaced. The bracket part numbers listed are NOT new numbers and there are no current changes to these specific part numbers. We are working to remove the note from the EPC. However, depending on when and how often your store's EPC is updated, the Note may still be present.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION