

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [ElsaWeb Newsletter](#) section in the Technician References menu.

VW ElsaWeb Newsletter



Das Auto.

Edition 24: February 18, 2013

Content

- [Tech Tips](#)
- [Feedback Corner](#)
- [Technical Bulletins](#)
- [Tech Tips](#)
- [Campaigns](#)
- [Updates](#)
- [Repair Manuals](#)
- [Wiring Diagrams](#)
- [Suggestions](#)



Tech Tips

All Tech Tips have been transferred to ElsaWeb. Over the next few months we will be reviewing all Tech Tips for their validity and adding metadata to give a more relevant results list. We appreciate your patience during this process.

Feedback Corner

This week's feedback is from Travis regarding 2009 Routan Repair Manual. He states:

"Under differential seal replacement in the repair manual tool C-3995-A is used to install the seal, this tool number is not in the tool catalog or anywhere in the Routan tool list."

This feedback was reviewed by the Service Information Team and was fixed. We really appreciate you sending in feedback to help improve the quality of the repair information.

Feedback Status		
New	Completed	To Factory
21	22	5

*Please note that this feedback feature is not the place to obtain technical assistance on Volkswagen vehicles, or to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create a Volkswagen Technical Assistance ticket and contact the Volkswagen Technical Helpline at (800)-678-2389.

[Back to top](#)

Technical Bulletins

69 13 01 - Airbag Warning Lamp Illuminated in Instrument Cluster, DTC B101614 Stored in Airbag Control Module					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf,GTI, Jetta SportWagen	2010–2013	All	All	All	All
Jetta Sedan	2011–2013	All	All	All	All
Passat	2012–2013	All	All	All	All
Airbag lamp in instrument cluster may illuminate due to unfastened connector for passenger airbag warning lamp. Production Solution: Information only.					

91 13 05 - Update Programming RCD-510 Radio (Premium 8)

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta	2012	All	All	AJ_CM000132 AJ_CM300030	AJ_CM133019 AJ_CM473994
Jetta	2013	All	All	AJ_DM212000	AJ_DM223599
Hybrid Jetta	2013	All	All	AJ_DM200037	AJ_DM242902
Jetta Sportwagen	2012 2013	All	All	AJ_CM600055 AJ_DM600610	AJ_CM714823 AJ_DM632613
Beetle	2012 2013	All	All	AT_CM608714 AT_DM605301	AT_CM666411 AT_DM630841
Golf/GTI	2012 2013	All	All	AJ_CW000164 AJ_DW014773	AJ_CW355364 AJ_DW076186
Eos	2012 2013	All	All	AH_CV000010 AH_DV000129	AH_CV022692 AH_DV002843
Passat	2012 2013	All	All	A3_CC000237 A3_DC000133	A3_CC111168 A3_DC027988
CC	2012 2013	All	All	AN_CE500020 AN_DE517090	AN_CE553133 AN_DE534178
Tiguan	2012 2013	All	All	AX_CW000602 AX_DW000363	AX_CW611172 AX_DW542347

Programming contained in software level(s) 0007, 0008, 0009, 0010, 0011, 0012, 0013, 0014, 0015, 0016 for certain RCD-510 Radio (Premium 8) radios may cause Bluetooth audio quality complaints for model year 2012 (SVM 383F). Programming contained in software level 0006, 0007, 0008 for certain RCD-510 Radio (Premium 8) radios may cause Bluetooth audio quality complaints for model year 2013 (SVM 37DC).

Production Solution: Model Year 2012 and 2013 running software change.

91 13 06 - Supersedes T.B. V911222 dated October 8, 2012 to include 9ZR radio identification.

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2009–2013	All	All	All	All

To understand how to identify the various Bluetooth systems by:

- Visual Identification
 - PR Code
- Part Number

Production Solution: Not applicable.

[Back to top](#)

Tech Tips

Currently, the Service Information Team is working to move the Tech Tips to ElsaWeb. The Team has transferred the majority of the 2007–2012 Tech Tips to ElsaWeb and is continuing to work to transfer all Tech Tips over the next few months. The Team thanks you for your patience during this transition.

64-13-01TT - Beetle Convertible – Door Window Height Adjustment Dimensions

Model(s)	Year	Eng. Code	Trans. Code
Beetle Convertible	2013	All	All

When adjusting a front door window, be aware that the height adjustment dimensions are as follows.

- Insertion at dimension “a” (near a-pillar): 7 mm +/- 1 mm
- Insertion at dimension “b” (near side window): 6 mm + 1 mm (note this is not +/-)

26-12-02TT - Passat TDI – AdBlue Level Reset Procedure

Model(s)	Year	Eng. Code	Trans. Code
Passat TDI	2012–2013	All	All
<p>To reset the AdBlue level indicator after filling, use Guided Fault Finding Function/Component selection to perform the SCR system functions test plan, available under Drivetrain > 01 – CKRA – Engine – J623 > 01-systems capable of self-diagnosis > 01 – Diesel-direct fuel inj. and glow plug system EDC 17 > 01 – Engine electronics functions. After starting test plan, make selection to "Set reducing agent fill level to full".</p> <p>If SCR related faults were stored in ECM before AdBlue tank was refilled, it may be necessary to complete a service regeneration to shut off AdBlue level indicator.</p>			

87-11-03TT - Passat with Dual Zone Climatronic – One Zone Colder / Warmer Than the Other

Model(s)	Year	Eng. Code	Trans. Code
Passat	2012–2013	All	All
<p>For concerns of one zone with no heat or blowing colder / warmer than the other on vehicles with dual zone Climatronic, first check the linkage between the actuator motor V158 and the left temperature blend door for proper installation, and/or damage. Linkage is number labeled 2 in the picture below. If the linkage is ok, proceed with normal diagnostics such as fault code and refrigerant charge checks.</p>			

[Back to top](#)

Campaigns

No new Campaigns in ElsaWeb.

[Back to top](#)

Updates

91K3 – RHR Radio Software (NVLW)					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Routan	2011–2012	All	All	2V4___DG_BR640622	2C4___DG_CR425164
<p>Vehicle must meet all of the following criteria:</p> <ul style="list-style-type: none"> • Procedure is valid only for vehicles that show the 91K3 code in ElsaWeb, Campaign/Action Information screen on the day of repair. <ul style="list-style-type: none"> • If the vehicle is sold it must be within the NEW VEHICLE LIMITED WARRANTY • Procedure must be performed within the allotted time frame stated in this UPDATE. • Procedure must be performed on applicable vehicles in dealer inventory prior to sale. 					

[Back to top](#)

Repair Manuals

Elsa Name	Model	Book Updated	Reason
1K2	Jetta Sedan 2005–2010	Body Interior	Feedback #770811
1K5	Jetta Sportwagen 2009	Body Interior	Feedback #770811
AJ5	Jetta Sportwagen 2010>	Body Interior	Feedback #770811
162	Jetta Sedan 2011>	Direct Shift Gearbox	Factory Update
1K2	Jetta Sedan 2005–2010 GLI 2008–2009	Direct Shift Gearbox	Factory Update
1K5	Jetta Sportwagen 2009	Direct Shift Gearbox	Factory Update
AJ5	Jetta Sportwagen 2010>	Direct Shift Gearbox	Factory Update
162	Jetta Sedan 2011>	Electrical Equipment	Factory Update

162	Jetta Sedan 2011>	Engine Mechanical, Fuel Injection and Glow Plug	Feedback# 748030, 767731
1K2	Jetta Sedan 2005–2010 GLI 2008–2009	Engine Mechanical, Fuel Injection and Glow Plug	Feedback# 748030, 767731
1K5	Jetta Sportwagen 2009	Engine Mechanical, Fuel Injection and Glow Plug	Feedback# 748030, 767731
AJ5	Jetta Sportwagen 2010>	Engine Mechanical, Fuel Injection and Glow Plug	Feedback# 748030, 767731
7P5	Touareg 2011>	Engine Mechanical, Fuel Injection and Glow Plug	Factory Update
16, 162	Jetta Sedan 2011> GLI 2012>	Fuel Supply System	Factory Update
1J, 9B, 9M	Jetta Wagon, Golf, GTI, Jetta Sedan 1999–2005	Generic Scan Tool	Feedback #726857
7P5	Touareg 2011>	Maintenance Procedures	Factory Update
162	Jetta Sedan 2011>	Manual Transmission	Factory Update
1K2	Jetta Sedan 2005–2010 GLI 2008–2009	Manual Transmission	Factory Update
1K5	Jetta Sportwagen 2009	Manual Transmission	Factory Update
AJ5	Jetta Sportwagen 2010>	Manual Transmission	Factory Update
1J, 9B, 9M	Jetta Wagon, Golf, GTI, Jetta Sedan 1999–2005	Heating, Ventilation and Air Conditioning	Feedback #662152
162	Jetta Sedan 2011>	Manual Transmission	Correction
1K2	Jetta Sedan 2005–2010 GLI 2008–2009	Manual Transmission	Correction
1K5	Jetta Sportwagen 2009	Manual Transmission	Correction
AJ5	Jetta Sportwagen 2010>	Manual Transmission	Correction

[Back to top](#)

Wiring Diagrams

No new Wiring Diagrams in ElsaWeb.

[Back to top](#)

Suggestions:

Please send comments or suggestions to: vwoa.WorkshopInformation@vw.com

[Back to top](#)

© 2012 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.