

SB-10054490-9136

Repair Notice

813-2

Section

Satellite Communication - 063

Description

Model 579 Qualcomm Speaker Missing

Release Date

9/10/2013

Introduction

Peterbilt has determined that certain Model 579 vehicles were built with Qualcomm capabilities and the Qualcomm speaker was not installed.

Expiration Date: September 10, 2014

Resolution

Remove the speaker bezel above the drivers head and locate the speaker wiring, plug the wiring into the speaker and install the speaker into the cutout.

Warranty

Peterbilt will reimburse for 0.5 hours labor for connecting the wire to speaker and installing the speaker.
For vehicles identified in SIR with "813-2", perform the repair to add a speaker and file a long form claim for **813-2**.

For Field...	Enter...
Failure Location	052-003-003
Failure Type	700
Claim Type	C

Campaign Number	813-2
SRT 063-001	0.5 hours

Parts

Peterbilt will reimburse for dealers for parts, dealer net + 30%.

Quantity	Part Number	Description
1	W3506GM	Qualcomm Speaker
2	S34-6003-0525TP00B	Fastener PSD2-2

Labor

Peterbilt will reimburse for 0.5 hours labor.

Procedure

- 1) Locate and remove the speaker bezel located just above the drivers head
- 2) Locate the wires that connects to the speaker and connect them to the speaker (speaker is marked with – and + terminals).
 - a) J335 attaches to the + terminal
 - b) J336 attaches to the – terminal
- 3) Fasten the speaker to the header and reinstall the speaker bezel

Attachments

[813-2 Chassis List](#)

[813-2 Sample Customer Letter](#)

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2013 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).