



Service Bulletin 511

Strictly Confidential

June 2014

Affected Models **Sprint GT ABS**

VIN Range **VIN 662826 to VIN 666329**

Markets **Australia and United Kingdom**

Subject **Cockpit Subframe**

Background Information

We have identified a need to carry out the following additional checks at PDI or at the motorcycles next visit to the dealership:

- To check the torque of the cockpit subframe to main frame nuts and bolts.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Identification of Affected Motorcycles

Sprint GT ABS listed in the VIN range above.

Warranty Claim Instructions

Fault code 02306091

Repair code 99511

Repair time allowance 0.06 hrs

Genuine Parts Information

Genuine parts Not applicable

Genuine Parts Ordering Instructions Not applicable

Genuine Parts Return Instructions Not applicable

Other Instructions

Before returning the motorcycle to the customer, download the latest tune to the engine control module using the current version of the Triumph diagnostic software.

Once completed, please mark the Service Record Book that the requirements of this bulletin have been complied with.



Cockpit Subframe to Main Frame Nuts and Bolts

Complete the checks as described in the procedure detailed below.




Warning

Throughout the following procedure, ensure that the motorcycle is stabilised and adequately supported to prevent the risk of injury from the motorcycle falling.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- The modified motorcycles can be identified by checking the 'VIN Enquiry' on Triumphonline.net.

1. Check and, if necessary, tighten the cockpit subframe to main frame nuts and bolts to **30 Nm**.



1. Nuts
2. Bolts
3. Cockpit subframe

Circulation

(Initial and date when read and return to central file holder)

Service Manager	Parts Manager	Sales Manager	Workshop Supervisor	Technician 1	Technician 2