

[Next Unread Message](#)**View Message**

Sent on 07 07 2014 **Expires on** 07 21 2014
From Parts and Service Division
Subject Request for Visit: 2013 Accord L4 Oil Leak at Head Cover Gasket

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
RE: Request for Visit: 2013 Accord L4 Oil Leak at Head Cover Gasket

This message is solely directed to Honda dealership personnel; please handle accordingly.
Print this iV message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda (AHM) is investigating certain 2013 Accord L4s with a complaint of oil leak at the head cover gasket. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to your attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. L4 model only.
2. VIN must start with 1HG.
3. VIN must be within the following range:
1HGCT1...DA003166 to 1HGCT1...DA020020 (2 Door)
1HGCR2...DA054873 to 1HGCR2...DA184507 (4 Door)

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.