

Measure M in process

Measure no. US 5321477-03	Subject CD radio: AUX port, no connection of mp3 player etc.	
Status date (mm/dd/yy) 9/10/14	Status Accepted	PQM Problem reference
Date created (mm/dd/yy) 9/10/14	Created by Martin Bumba	Organization US, MOT
Release date (mm/dd/yy)	Approved by	Dealer release Allow automatic release

Vehicles affected

E series K26	Engine 2-ZYL	Body
Production period (from/to) (mm/dd/yy) 7/31/04 / 12/30/06	Comment on production period	Feedback (all cases relating to measure up to) (mm/dd/yy)

Complaint

For vehicles manufactured before January 2007, the radio operating instructions specify that an MP3 player, amongst other items, can be connected to the AUX In port on the CD radio.

Cause

Error in the radio operating instructions.

Measure

It is NOT possible to connect an audio source (e.g. MP3 player) to the AUX In port.

It is also not possible to retrofit the connection kit for the MP3 player on vehicles manufactured before January 2007.

Complaint

Fault location	Fault type	Fault place
Connecting AUX-IN / USB device	Communication fault	

Cause

#	Fault location	Fault type	Fault place
1	01/40 OWNER'S HANDBOOK / ON-BOARD LITERATURE	Labelling wrong / faulty	
Repair Task	Special Clearance	Area	
No action	No	Electrics/Electronics	

Fault code

CIP / DIS

System	State	Version
--------	-------	---------

Tech. Office report

Report no.	Subject	Link Condition
------------	---------	----------------

5339905	CD radio: AUX port, no connection of mp3 player etc.	Approved
---------	--	----------

[View](#)[Edit](#)**Measure AG**

Measure no.	Subject
-------------	---------

AG 5321477-02	CD radio: AUX port, no connection of mp3 player etc.
---------------	--

[View](#)**Progman / DIS / ISTA / ISTA/P**

System	State	Version
--------	-------	---------

© 2002-2014 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.