



Service Bulletin

File in Section: -

Bulletin No.: PIC6044

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Rear End / Decklid Spoiler Replacement Labor Code Information

Models: 2014 - 2015 Chevrolet Impala
With Dealer-Installed Spoiler (RPO SB2) or Plant-Installed Spoiler (RPO T43)

It has been found that the incorrect labor code could be used when replacing a Dealer-Installed GM Accessories Rear End / Decklid Spoiler.

Specific labor codes have been set up in the following location of the labor time guide relative to the repair / replacement of GM Accessories:

General Information > Dealer Installed GM Accessory Repairs

Please use the appropriate labor code reflected in the matrix below when replacing a rear end / decklid spoiler.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
0522210	Rear End Spoiler Replacement - Dealer Installed (RPO SB2)	Use Published Labor Operation Time
1011290	Rear End Spoiler Replacement - Plant Installed (RPO T43)	Use Published Labor Operation Time