

Date	Expiration	Release	Page
05.2015	05.2017	1	1(2)

Revision A This version replaces previous versions
June 02, 2015 Added vehicles not covered by production

LEFT HAND SUN VISOR REPLACEMENT Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, replace sun visor on the left side of the driver's seat by an updated version..

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2014- 215	Single Units: 2PCG33495EC735590 and 2PCG33498EC735602. And From 4RKG33497F9737001 up to 4RKG33490F9737051 incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order kit SP15-317 which includes the following parts:

Part No.	Description	Qty
901374	Sun Visor Rev "E"	1

NOTE
Material can be obtained through regular channels.

PROCEDURE

 DANGER
Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

- 1) Above the driver's toll window, remove the original sun visor.
- 2) Install the new one and hand-tighten the set screw. (Fig. 1)




Figure 1

PARTS / WASTE DISPOSAL

Return replaced parts to Prevost with A.F.A. for full reimbursement.
 Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately half an hour (30 min).

OTHER

VBC Bulletin	N/A
Fail Code	18.02
Defect Code	09
System Condition	B
Causal Part	901374

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.